

ENVIRONMENTAL PROTECTION AGENCY STATE OF ILLINOIS USEPA	RECORDS CENTER REGION 5
LPCFC055 C	(88)
$(1) \qquad (8) \qquad (9) \qquad (1) $	
INSPECTION REPORT - SITE INVENTORY NO. 16305001	487654
ST. CLAR Co L.P.C. Region (11) Date 08	2978
$\begin{array}{cccccccccccccccccccccccccccccccccccc$	$(25)_{A/}$
tairment City / Metro Letter Sent (Ye	es or No)
(Location) (Responsible Party)	(26)
Samples Taken: Yes () No (X) Time: From $\frac{C}{I}$: $\frac{30pm}{I}$ Weather $\frac{780}{I}$	1/2/15
Fround Water() Surface() Other() To 02:154 m Inspector	m as Kom
Photos Taken: Yes () No (X) Interviewed No (1) Inspector /	(28)
Previous Inspection 81574 Previous Correspondence 82874 Site Open:	Yes() No(X)
OPERATIONAL STATUS: TYPE OF OPERATION: AUTHORIZA	
Operating () Sanitary Landfill (X) Storage () E.P.A. Pe	
Temporarily Closed () Random Dump () Salvage () Variance	()
Closed Not Covered () Other () A.C.D. () 21(e)	()
Closed and Covered (X) Quantity Received Daily(1-6) Board Ord	ler ()
(30) Illegal ((5) (X) <u>.</u>
SITE EVALUATION	~ (31)
Leachate: Ponded on site (X)	32
Flowing on site (X)	ED_{34}^{33} —
Seeping (X)	25 ——
Observed garbage() refuse() in standing water (X) AUG 31 197	
Flow entering surface water (5)	37
Flow leaving site (1-3)	38
Open Burning: Observed (5) STATE OF ILLIN	2.C. 39 —
Underground fire (5)	OIS . 40 <u>5</u>
Evidence of recent open burning (5)	41
Insufficient fire protection equipment provided (2)	
Daily Cover: Not provided on previously deposited refuse (5)	
Not provided on previous operating day (4)	
Inadequate depth over entire area (3)	
Inadequate depth over only a portion of area (1-2)	
Intermediate Cover: Inadequate depth in portion(s)() or entire() required areas Final Cover: Inadequate depth in some areas (1-3)	
Inadequate depth over entire area 60 days after area closure (4)	
None 60 days after area closure (5)	
Unloading not supervised (3)	
Refuse not deposited at toe of slope ()	
Inadequate spreading and compacting ()	
Insufficient operable equipment on site as required () (2 ea. 2-8)	52
Operational roads unsatisfactory ()	
Blowing litter(), dust nuisance observed(), Odor detected() (1 ea. 1-3)	
Permit() Board Order() Violation noted (2 ea. 2-4)	
Liquids() Solids() not permitted (5)	
Inadequate: Shelter() Sanitary Facilities() Emergency Communications()(1 each	
Scavenging by: Operator() Others() observed (1-3)	58
Salvaging Observed(): Improperly conducted in:Location()Operation()Storage()	
Evidence of vectors observed () (1-3)	
Animal feeding observed () (1-3)	
	
General Compliance () Improvement Needed (X) Improvement Obs	served ()


Signature of operator does not necessarily imply agreement with the above noted observations.

LPC-5 (Rev. 6-75-500)

Signature _____Owner/Operator







I. GENERAL

3.3

₹.

0

This report and the accompanying plans summarize the results of the engineering analysis and design associated with a proposed land reclamation project that is to be conducted by Metro Disposal Systems, Inc., of Belleville, Illinois.

The proposed land reclamation project is located on property owned by the Penn Central Railroad in the area known as the Roselake Yards in St. Clair County, Illinois. The specific piece of property being developed is north of the Eastward yard and is located between the City Limits of Fairmont on the east and the western railroad property on the west line, and is bounded on the north by Collinsville Road, which was formerly designated as U. S. Route 40.

The project has been divided into three (3) separate parts designated as Phase "A", which is now under construction, Phase "B" and Phase "C".

This report pertains primarily to the development of the area designated as Phase "B". It encompasses an area bounded on the south by the most northerly track of the Penn Central Railroad, on the west by the most westerly line of section 8, on the north by Collinsville Road, which was formerly designated as U. S. Route 40, and on the East by an existing dike running north and south, starting 700" + east of the western line of Section 8 along the south right-of-way line of Collinsville Road.

The Phase "C" portion of the project will be located on the remainder of the property and plans are being developed for operations in this area when Phase "B" is nearly completed.

II. SITE DRAINAGE

At the present time, the property is drained along the north by an open drainage ditch along Collinsville Road which drains to the west.

The site is drained on the west by a drainage ditch which runs parallel to the west property line to approximately 100' north of the most northern track of the Penn Central R. R; the ditch then turns in an easterly direction and runs parallel to the most northern track of the Penn Central R. R. picking up the drainage of the remaining area. An analysis of the drainage conditions at the site have been made and recommendations for procedures to accomplish drainage of the site during the construction

-1-